

**** OCR, Feeders and Subs are included. Fuses, transformers and individuals are not. ****

AUGUST 2020

08/04/2020 – 12:28PM

Bunker Hill – tree thru line, off 2 hrs

08/06/2020 – 11:17AM

Bunker Hill – bird on transformer between the bushing & lightning arrester, off 1 ½hrs

08/09/2020 –

3:03AM - Taylor Springs – storm/rain; catfish on the line, dropped by bird, off 2hrs

10:00AM -Womac – storm/lightning; bad transformer – off 2hrs

08/10/2020 –

5:09PM - Witt – storm/hail/lightning – tree thru line, off 2hrs

6:55PM - Nutwood – lightning, storm – trees in line, off 2 ½hrs

08/11/2020 –

10:30AM - Witt – tree thru line, off 2hrs

12:40PM -Newbern – Power Supplier replacing equipment in sub, off 1hr

10:03PM - Nutwood – trees in line, off 1hr

08/16/2020 – 9:28AM

Jerseyville – tree thru line, off 2hrs

08/17/2020 –

11:18AM - Rinaker - trees in & thru line, off 3hrs

1:20PM - Womac – linemen, new construction installing poles WO#2007405, off 1hr

08/21/2020 – 1:03PM

Bunker Hill – Machinery bumped line knocking it down, off 1hr

08/23/2020 – 3:38PM

Newbern – wires wrapped around each other, off 2hrs

08/27/2020 – 3:54PM

Newbern - tree thru line, lines down, off 2 ½ hrs.

08/28/2020 –

9:35AM - Rinaker – line maintenance, linemen changing out a 3-phase pole, off 1hr

12:16PM - Rinaker – had operation on East & South feeder. Only C-phase OCR was locked out

on South feeder at sub. Picked up without a problem. Patrolled out & nothing was in it, off 1hr.

08/29/2020 – 8:47AM

Brighton – primary u.g. conductor blown, no cause found, off 1 ½ hrs.