

**\*\* OCR, Feeders and Subs are included. Fuses, transformers and individuals are not. \*\***

**SEPTEMBER 2020**

**09/01/2020 – 4:42PM**

Brighton – Bad OCR, off 2hrs

**09/02/2020 – 4:16AM**

Brighton – bad suspension insulator, transformer pole top burned, off 2hrs

**09/08/2020 – 3:42PM**

Newbern – tree on the line, off 2hrs

**09/13/2020 – 9:50AM**

Butler – planned outage, re-sagged wire in 4 different spans; put up fault indicators, off 2 ½ hrs.

**09/20/2020 – 2:29PM**

Bunker Hill – tractor in lines; lines down; broken poles, off 6 hrs.

**09/28/2020 –**

12:17PM Staunton – wind/dead tree hit line slapping together, off 1 ½ hrs.

6:04PM - Staunton – trees thru line; lines down, off 2hrs

**09/29/2020 – 8:51AM**

Womac – bird on pole; pole top on fire, off 1 ½ hrs.

**09/30/2020 – 10:51AM**

Brighton – planned outage/ wo# 2007403 linemen working on 3-phase line extension; setting poles in line, off 1 ½ hrs.