

OCTOBER 2019

10/01/19 – 12:14 PM

Womac - wires wrapped together, off 1hr.

10/02/19 –

8:42 AM - Bunker Hill – Tree trimmers knocked line together tripped OCR #937, off 2hrs.

9:00 AM - Womac – JF (contractor) took outage to replace overhead single phase to three phase overhead WO# 1902403, off 4hrs.

10/04/19 – 6:01 AM

Brighton – broken insulator, off 1 ½ hrs.

10/05/19 – 5:42 PM

Rinaker – member got in line, off ½ hr

10/08/19 –

9:50 AM - Butler - OCR #891, squirrel – blown transformer, off 2hrs.

4:56 PM - Jerseyville – bad U.G., off 6 hrs.

10/09/19 –

12:00 PM - Staunton – OCR #873 - private tree trimmer got in line tore neutral down, off 1hr

8:00 AM - Jerseyville – took down portable substation and energized new substation transformer, off 6 hrs.

10/10/19 –

10:35 PM - Taylor Springs – tree thru line, off 2hrs.

10:45 PM - Jerseyville – lightning, broken stinger wire, off 4hrs.

10/11/19 – 12:04 PM

Womac – Bad transformer, off 3hrs

10/12/19 –

12:30 PM - Taylor Springs – OCR #905, line burnt down due to bad connection, off 3 ½ hrs.

2:27 PM - Brighton – Wind, bad connections members wires, off 2hrs

10/14/19 – 4:26 PM

Witt – broken cut-out, off 1 1/2hrs.

10/17/19 – 10:54 AM

Taylor Springs – Planned outage to change out 3-phase pole, off 1hr 10mins

10/18/19 – 3:59 AM

Rinaker – bad U. G. primary conductor, off 3 ½ hrs.

10/21/19 –

7:10 AM - Bunker Hill – rain, tree thru line, off 2hrs.

12:34 PM - Nutwood – rain, tree down in private, long span line down, off 3hrs.

10/26/19 –

10:30AM - Witt – rain, tree thru line, off 4hrs.

8:44 PM - Newbern – tree in line, line down, off 4hrs.

10/29/19 –

7:04 AM - Newbern – Wind, tree limb on phase – off 3 1/2hrs

10:00 AM - Rinaker – planned outage, to c/o regulators & Pole, off 4hrs

3:57 PM - Staunton – raccoon blew fuse on U. G primary conductor, off 1hr.

10/30/19 – 8:26 AM

Taylor Springs – broken insulator, line down, off 2 ½ hrs.